

Test Report

Number: GZHH00371287S1

Applicant: CIXI PNEUFLEX PNEUMATIC COMPONENTS
CO.,LTD
NO.2388, QINGSHAONIANGONG NORTH ROAD,
KANDUN STREET, CIXI, CHINA, 315303

Date: Jul 21, 2020

Attn: DELLA JI

*This is to supersede Report No.
GZHH00371287 dated Jul 17,
2020*

Sample Description:

One (1) piece of submitted sample said to be **316 Stainless Steel Tube Fittings**
Country of Origin : China

Tested Sample



Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

Conclusion:

Tested sample	Standard	Result
Tested component(s) of submitted sample	FDA General Recognized As Safe (GRAS)	Pass

Authorized by:

For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch, Hardlines

Victor T.J. Wang
Assistant General Manager



Test Report

Number: GZHH00371287S1

Tests Conducted

1 Total Chromium content

By acid digestion followed by Inductively Coupled Plasma Emission Spectroscopic analysis.

<u>Element</u>	<u>Result (%)</u>	<u>Reporting limit</u>	<u>Limit</u>
	<u>(1)</u>	<u>(%)</u>	<u>(%)</u>
Chromium (Cr)	17.17	0.01	16 min

Tested Component(s): (1) Silver color SS316 stainless steel (joint tube).

Date sample received: Jul 08, 2020

Testing period: Jul 08, 2020 to Jul 13, 2020



Test Report

Number: GZHH00371287S1

Tests Conducted

Reference photo



Remark : The products in the reference photos are not tested in this report. It's declared by the applicant that the materials of those items are identical to the particular tested sample. They are just included in the report for reference.

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band $w = U$) except designation from the customer, regulation or test specification.

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.



To: CIXI PNEUFLEX PNEUMATIC COMPONENTS
CO.,LTD

Ref: FC-200 (0899)

Attention: DELLA JI

Date: Jul 21, 2020

Re : Report Revision Notification

Intertek Testing Services Report Number GZHH00371287 Dated Jul 17, 2020

Please be informed that all the content recorded in the above captioned report will be void. This captioned report is now supersede by a revised Intertek Testing Services Report, GZHH00371287S1.

Details of report amendment:

1. Modify Description to be 316 Stainless Steel Tube Fittings.
2. Modify Tested Component(s): (1) Silver color SS316 stainless steel (joint tube).

Thank you for your attention.

Authorized by:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch, Hardlines



Victor T.J. Wang
Assistant General Manager

